MOTORENN 151-POINT INSPECTION

MOTORENN

MAKE: FORD | MODEL: GT | YEAR: 2006 | VIN: 400912

	VEHICLE HISTORY	CHECK OFF
1	Matching vins	✓
2	Clean Carfax report	✓
3	No accidents	✓
4	No salvage/lemon title	✓
5	Maintenance records	✓
6	No open recalls	✓

NOTES :

	VEHICLE SERVICE	CHECK OFF
7	Engine oil and filter (If within 3 months or 2500 miles of service interval or no service records exist)	✓
8	Engine air filter (If within 3 months or 2500 miles of service interval or no service records exist)	✓
9	Cabin air filter (If within 3 months or 2500 miles of service interval or no service records exist)	✓
10	Brake fluid	✓
11	Coolant	✓
12	Transmission fluid	✓
13	Differential fluid	✓
14	Brake pads	✓
15	Brake rotors	✓
16	Wiper blades	✓
17	Tires	

NOTES :

	FACTORY ITEMS	CHECK OFF
18	Key check (Number)	2
19	Original window sticker	✓
20	Original manuals	✓
21	Factory floor mats	✓

NOTES :

	AFTERMARKET PARTS	CHECK OFF
22	Factory exhaust	—
23	Factory wheels	✓
24	Factory floor mats	✓
25	Factory audio unit	✓

	AFTERMARKET PARTS (CONT.)	CHECK OFF
26	Factory seats	✓
27	Any other Items?	

NOTES : Borla Exhaust.

	ROAD TEST	CHECK OFF
28	Starting	✓
29	No idle at vibration	✓
30	No abnormal engine noise	✓
31	Smooth acceleration	✓
32	Engine operating temperature	✓
33	Smoothness in drivability	✓
34	Shifting smoothness	✓
35	No clutch slippage (Manuals)	✓
36	Manual transmission operation	✓
37	No transaxle noise	✓
38	No transmission noise	✓
39	No CV joint/drive axle noise	✓
40	Braking straight	✓
41	No brake noise	✓
42	Parking brake operation	✓
43	Steering effort (No drifting)	✓
44	No steering wheel play	✓
45	Cruise control operation	✓
46	Horn operation	✓
47	No excessive wind noise/squeaks/rattles	✓
48	Speedometer operation	✓
49	Heater/defroster operation	✓
50	A/C cooling performance	✓
51	No steering wheel vibration	✓
52	No body/suspension noise	✓

NOTES :

	UNDERHOOD	CHECK OFF
53	Battery (Condition, age, charge)	✓
54	Alternator (Belt condition, charging)	✓
55	Water pump (No leaks, no noise)	✓
56	Fuel System operation (Leaks)	✓
57	Radiator (No leaks, no damage)	✓
58	A/C condenser (No corrosion)	✓
59	Cooling fan operation	✓
60	Coolant hoses	✓

	UNDERHOOD (CONT.)	CHECK OFF
61	Engine mounts	✓
62	Transmission mounts	✓
63	Engine (No oil leaks)	✓
64	No transmission leaks	✓
65	No coolant leaks	✓
66	No CV joint and boot leaks or cracks	✓
67	Suspension height	✓
68	Bushing condition	✓
69	No power steering rack leakage	✓
70	Exhaust system condition	✓
71	Emissions compliant	✓
72	Engine bay clean	✓

NOTES :

	EXTERIOR	CHECK OFF
73	No wheel/rim damage	✓
74	Valve stem condition	✓
75	Valve stem cover present	✓
76	Wheel lug nuts properly torqued	✓
77	Locking wheel lug nut key (If applicable)	N/A
78	Spare tire condition	N/A
79	Headlights high/low beam	✓
80	Brake lights	✓
81	Turn signals	✓
82	Parking lamps	✓
83	Fog lights	✓
84	Running lights	✓
85	License plate light	✓
86	Tail lights	✓
87	Back-up lights	✓
88	Emergency flasher	✓
89	Sunroof glass condition	N/A
90	Side mirror condition	✓
91	Grille condition	✓
92	Drivers side front fender condition	✓
93	Driver side doors condition	✓
94	Drivers side rear quarter panel condition	✓
95	Passengers side front fender condition	✓
96	Passengers side doors condition	✓
97	Passengers side rear quarter panel condition	✓

NOTES :

MOTORENN 151-POINT INSPECTION

MOTORENN

MAKE: FORD | MODEL: GT | YEAR: 2006 | VIN: 400912

	EXTERIOR (CONT.)	CHECK OFF
98	Front bumper condition	✓
99	Hood condition	✓
100	Trunk condition	✓
101	Rear bumper condition	✓
102	Roof paint condition	✓

NOTES :

	INTERIOR	CHECK OFF
104	No water leaks inside	✓
105	Fuel gauge operation	✓
106	Temp gauge operation	✓
107	All warning lights illuminated with ignition on	✓
108	Dash light operation	✓
109	Audio system function	✓
110	Bluetooth operations	N/A
111	Satellite radio operation	N/A
112	Steering wheel controls	N/A
113	Navigation operation	N/A
114	Rear camera operation	N/A
115	Clock operation	✓
116	Steering wheel tilt operation	✓
117	Sunroof operation	N/A
118	Sunshade operation	✓
119	Headliner condition	✓
120	Cigarette lighter operation	✓
121	Alarm/theft system operation	✓
122	SRS airbags condition	✓
123	Outside mirror operation (Left and right)	✓
124	Rearview mirror operation	✓
125	Window operation	✓
126	Door lock operation	✓
127	Seat belt operation	✓
128	Seat upholstery condition	✓
129	Power seat operation	N/A
130	Seat heater operation	N/A
131	Seat cooler operation	N/A
132	Headrest movement operation	N/A
133	Rear defrost operation	✓

NOTES :

	INTERIOR (CONT.)	CHECK OFF
134	Inside light operation	✓
135	Warning chime operation	✓
136	Glove box and light operation	✓
137	Luggage compartment tools present	✓
138	Trunk lid release and light operation	✓
139	Liftgate operation	N/A
140	Fuel door release	✓
141	Hood release operation	✓
142	No interior odors	✓

NOTES :

	DETAILING	CHECK OFF
143	Carpets vacuumed	✓
144	Car washed	✓
145	Car polished and waxed	✓
146	Tire dressing applied	✓
147	Leather cleaned	✓
148	Engine compartment cleaned	✓
149	Trunk vacuumed	✓
150	Interior glass and trim wiped down	✓
151	Exterior glass wiped down	✓

NOTES :

NOTES :

5552 W Manchester Ave, Suite A, Los Angeles, CA | (424) 363-7410 | www.motorenn.com