Inspection Information

Inspection Date: 2026-10-07 **Inspection Location:** Los Angeles, CA **Client Name:** Motorenn Inc
Client Phone: 424-363-7410 **Client Email:** service@motorenn.com
Client Address: 5255 W 102nd Street **Seller:** Motorenn Inc
Year: 2019 **Make:** Porsche **Model:** 911
Mileage: 25604 **VIN:** WP0CB2A98KS136772 **Body Style:** Convertible
Transmission: Automatic **Engine:** 6 cylinder **Drive Type:** RWD
Inspector: Ryann Derrama **Inspector Phone:** **Inspector Email:**
Interior Color: Black **Exterior Color:** Silver

G = Good F = Fair P = Poor

Interior

G	F	P		
☑	☐	☐	1.	Fuel Door Release
☑	☐	☐	2.	Hood Release
☑	☐	☐	3.	Trunk Lid Release
☑	☐	☐	4.	Air Bags
☑	☐	☐	5.	Tilt/Telescoping Steering Wheel
☑	☐	☐	6.	Steering Wheel Controls
☑	☐	☐	7.	Horn
☑	☐	☐	8.	Windshield Wiper Operation/Controls
☑	☐	☐	9.	Windshield Washer Operation/Controls
☑	☐	☐	10.	Instrument Panel
☑	☐	☐	11.	Warning Lights
☑	☐	☐	12.	Warning Chimes
☑	☐	☐	13.	Air Conditioning
☑	☐	☐	14.	Heating System
☑	☐	☐	15.	Defogger/Defroster
☑	☐	☐	16.	Clock
☑	☐	☐	17.	Radio
☑	☐	☐	18.	Audio Player
☑	☐	☐	19.	Speakers
☑	☐	☐	20.	Lighter/Power Outlet(s)
☑	☐	☐	21.	Interior Courtesy/Map/Dome Light
☑	☐	☐	22.	Glove Box
☑	☐	☐	23.	Glove Box Light
☑	☐	☐	24.	Center Console
☑	☐	☐	25.	Sun Visors
☑	☐	☐	26.	Sun Visors Lights
☑	☐	☐	27.	Vanity Mirrors
☑	☐	☐	28.	Inside Rear View Mirror
☑	☐	☐	29.	Armrests

Interior

G	F	P		
☑	☐	☐	30.	Outside Mirror Operation/Controls
☑	☐	☐	31.	Door Locks Manual
☑	☐	☐	32.	Door Locks Automatic
☑	☐	☐	33.	Child Safety Locks
☑	☐	☐	34.	Window Controls
☑	☐	☐	35.	Door Handles
☑	☐	☐	36.	Heated/Cooled Seats
☑	☐	☐	37.	Seats
☑	☐	☐	38.	Seat Controls
☑	☐	☐	39.	Headrest
☑	☐	☐	40.	Seat Belts
☐	☐	☐	41.	Sunroof/Moonroof
☑	☐	☐	42.	Convertible Top
			43.	Headliner
☑	☐	☐	44.	Carpet
☑	☐	☐	45.	Floor Mats
☑	☐	☐	46.	Interior Trim
☑	☐	☐	47.	Door Panels
☑	☐	☐	48.	Luggage Compartment
☑	☐	☐	49.	Trunk Light
☑	☐	☐	50.	Jack and Tool Kit

Exterior

G	F	P		
☑	☐	☐	51.	Windshield
☑	☐	☐	52.	Wiper Blades
☑	☐	☐	53.	Windows
☑	☐	☐	54.	Rear Window
☑	☐	☐	55.	Mirrors
☑	☐	☐	56.	Head Lights
☑	☐	☐	57.	High Beams
☑	☐	☐	58.	Parking Lights
☑	☐	☐	59.	Turn Signals

Exterior

G	F	P		
☑	☐	☐	60.	Taillights
☑	☐	☐	61.	Brake Lights
☑	☐	☐	62.	Hazards
☑	☐	☐	63.	License Plate Lights
☑	☐	☐	64.	Reverse Lights
☐	☐	☐	65.	Fog Lights
☑	☐	☐	66.	Running Lights
☑	☐	☐	67.	Side Marker Lights
☑	☐	☐	68.	Body Panels
☑	☐	☐	69.	Front Bumper
☑	☐	☐	70.	Grille
☑	☐	☐	71.	Hood
☑	☐	☐	72.	Rear Bumper
☑	☐	☐	73.	Rear Hatch
☑	☐	☐	74.	Trunk
☑	☐	☐	75.	Left Front Fender
☑	☐	☐	76.	Left Front Door
☑	☐	☐	77.	Left Rear Fender
☐	☐	☐	78.	Left Rear Door
☑	☐	☐	79.	Right Rear Fender
☐	☐	☐	80.	Right Rear Door
☑	☐	☐	81.	Right Front Fender
☑	☐	☐	82.	Right Front Door
☐	☐	☐	83.	Roof
☐	☐	☐	84.	Roof Rack
☑	☐	☐	85.	Trim
☑	☐	☐	86.	Fuel Door
☑	☐	☐	87.	Paint

Tires

G	F	P		
☑	☐	☐	88.	Left Front Tire
☑	☐	☐	89.	Left Rear Tire
☑	☐	☐	90.	Right Rear Tire

© InspectARide.com

G F P

Tires

- [x] [ ] [ ] 91. Right Front Tire
- [ ] [ ] [ ] 92. Spare Tire
- [x] [ ] [ ] 93. Wheels
- [x] [ ] [ ] 94. Wheel Lug Nuts

Underbody

- [x] [ ] [ ] 95. Frame
- [x] [ ] [ ] 96. Overall Underbody Condition
- [x] [ ] [ ] 97. Exhaust System
- [x] [ ] [ ] 98. Catalytic Converter
- [x] [ ] [ ] 99. Transmission Mounts
- [x] [ ] [ ] 100. Transmission
- [x] [ ] [ ] 101. Differential/Drive Axle
- [x] [ ] [ ] 102. Universal Joints/CV Joints/Boots
- [x] [ ] [ ] 103. Power Steering
- [x] [ ] [ ] 104. Suspension
- [x] [ ] [ ] 105. Tie-Rods/Idler Arm
- [x] [ ] [ ] 106. Sway Bars
- [x] [ ] [ ] 107. Springs
- [x] [ ] [ ] 108. Shocks
- [x] [ ] [ ] 109. Control Arms
- [x] [ ] [ ] 110. Ball Joints/Bushings
- [x] [ ] [ ] 111. Rotors/Drums
- [x] [ ] [ ] 112. Calipers
- [x] [ ] [ ] 113. Parking Brake
- [x] [ ] [ ] 114. Brake Pads
- [x] [ ] [ ] 115. Brake Lines/Hoses/Fittings

Underhood

- [x] [ ] [ ] 116. Engine Oil
- [x] [ ] [ ] 117. Brake Fluid
- [x] [ ] [ ] 118. Coolant
- [x] [ ] [ ] 119. Power Steering Fluid
- [x] [ ] [ ] 120. Transmission Fluid
- [x] [ ] [ ] 121. Washer Fluid
- [x] [ ] [ ] 122. Transfer Case Fluid
- [x] [ ] [ ] 123. Engine Mounts
- [x] [ ] [ ] 124. Overall Engine Condition

G F P

Underhood

- [x] [ ] [ ] 125. Engine Belts
- [x] [ ] [ ] 126. Engine Hoses/Lines/Fittings
- [x] [ ] [ ] 127. Radiator
- [x] [ ] [ ] 128. Water Pump
- [x] [ ] [ ] 129. Coolant Recovery Tank
- [x] [ ] [ ] 130. Coolant Fans/Clutches/Motors
- [x] [ ] [ ] 131. Coolant Hoses
- [x] [ ] [ ] 132. Wiring
- [x] [ ] [ ] 133. Starter Operation
- [x] [ ] [ ] 134. Ignition Operation
- [x] [ ] [ ] 135. Battery
- [x] [ ] [ ] 136. Alternator
- [x] [ ] [ ] 137. Air Filter
- [x] [ ] [ ] 138. Fuel System Operation

Road Test

- [x] [ ] [ ] 139. Starting
- [x] [ ] [ ] 140. Idling
- [x] [ ] [ ] 141. Engine Noise
- [x] [ ] [ ] 142. Throttle
- [x] [ ] [ ] 143. Transmission Shift
- [x] [ ] [ ] 144. Clutch Operation
- [x] [ ] [ ] 145. Accelerating
- [x] [ ] [ ] 146. Steering Alignment
- [x] [ ] [ ] 147. Power Steering
- [x] [ ] [ ] 148. Cruise Control
- [x] [ ] [ ] 149. Braking
- [x] [ ] [ ] 150. ABS (Anti-Lock Braking System)
- [x] [ ] [ ] 151. Body/Suspension

Additional Notes

152. Additional Notes:

© InspectARide.com

Comments

88. Left Front Tire 6/32 2023
89. Left Rear Tire 6/32 1824
90. Right Rear Tire 6/32 1824
91. Right Front Tire 6/32 2023
114. Brake Pads Front pads 70%
Rear pads 70%
116. Engine Oil Oil change completed 10/2026
152. Additional Notes: Full front PPF

© InspectARide.com