



Inspection Information

Inspection Date: 2026-05-28

Client Phone: 424-363-7410

Client Address: 5255 W 102nd Street

Year: 2022

Mileage: 3313

Transmission: Automatic

Inspector: Ryann Derrama

Interior Color: Black

Inspection Location: Los Angeles, CA **Client Name:** Motorenn Inc

Client Email: service@motorenn.com

Seller: Motorenn Inc

Model: DBS

Body Style: Convertible

Drive Type: RWD

Inspector Email:

Make: Aston Martin

VIN: SCFRMHCV6NGT02698

Engine: 12 cylinder

Inspector Phone:

Exterior Color: Black

G = Good F = Fair P = Poor

G F P

Interior

- 1. Fuel Door Release
- 2. Hood Release
- 3. Trunk Lid Release
- 4. Air Bags
- 5. Tilt/Telescoping Steering Wheel
- 6. Steering Wheel Controls
- 7. Horn
- 8. Windshield Wiper Operation/Controls
- 9. Windshield Washer Operation/Controls
- 10. Instrument Panel
- 11. Warning Lights
- 12. Warning Chimes
- 13. Air Conditioning
- 14. Heating System
- 15. Defogger/Defroster
- 16. Clock
- 17. Radio
- 18. Audio Player
- 19. Speakers
- 20. Lighter/Power Outlet(s)
- 21. Interior Courtesy/Map/Dome Light
- 22. Glove Box
- 23. Glove Box Light
- 24. Center Console
- 25. Sun Visors
- 26. Sun Visors Lights
- 27. Vanity Mirrors
- 28. Inside Rear View Mirror
- 29. Armrests

G F P

Interior

- 30. Outside Mirror Operation/Controls
- 31. Door Locks Manual
- 32. Door Locks Automatic
- 33. Child Safety Locks
- 34. Window Controls
- 35. Door Handles
- 36. Heated/Cooled Seats
- 37. Seats
- 38. Seat Controls
- 39. Headrest
- 40. Seat Belts
- 41. Sunroof/Moonroof
- 42. Convertible Top
- 43. Headliner
- 44. Carpet
- 45. Floor Mats
- 46. Interior Trim
- 47. Door Panels
- 48. Luggage Compartment
- 49. Trunk Light
- 50. Jack and Tool Kit

Exterior

- 51. Windshield
- 52. Wiper Blades
- 53. Windows
- 54. Rear Window
- 55. Mirrors
- 56. Head Lights
- 57. High Beams
- 58. Parking Lights
- 59. Turn Signals

G F P

Exterior

- 60. Taillights
- 61. Brake Lights
- 62. Hazards
- 63. License Plate Lights
- 64. Reverse Lights
- 65. Fog Lights
- 66. Running Lights
- 67. Side Marker Lights
- 68. Body Panels
- 69. Front Bumper
- 70. Grille
- 71. Hood
- 72. Rear Bumper
- 73. Rear Hatch
- 74. Trunk
- 75. Left Front Fender
- 76. Left Front Door
- 77. Left Rear Fender
- 78. Left Rear Door
- 79. Right Rear Fender
- 80. Right Rear Door
- 81. Right Front Fender
- 82. Right Front Door
- 83. Roof
- 84. Roof Rack
- 85. Trim
- 86. Fuel Door
- 87. Paint

Tires

- 88. Left Front Tire
- 89. Left Rear Tire
- 90. Right Rear Tire



G F P

Tires

- 91. Right Front Tire
- 92. Spare Tire
- 93. Wheels
- 94. Wheel Lug Nuts

Underbody

- 95. Frame
- 96. Overall Underbody Condition
- 97. Exhaust System
- 98. Catalytic Converter
- 99. Transmission Mounts
- 100. Transmission
- 101. Differential/Drive Axle
- 102. Universal Joints/CV Joints/Boots
- 103. Power Steering
- 104. Suspension
- 105. Tie-Rods/Idler Arm
- 106. Sway Bars
- 107. Springs
- 108. Shocks
- 109. Control Arms
- 110. Ball Joints/Bushings
- 111. Rotors/Drums
- 112. Calipers
- 113. Parking Brake
- 114. Brake Pads
- 115. Brake Lines/Hoses/Fittings

Underhood

- 116. Engine Oil
- 117. Brake Fluid
- 118. Coolant
- 119. Power Steering Fluid
- 120. Transmission Fluid
- 121. Washer Fluid
- 122. Transfer Case Fluid
- 123. Engine Mounts
- 124. Overall Engine Condition

G F P

Underhood

- 125. Engine Belts
- 126. Engine Hoses/Lines/Fittings
- 127. Radiator
- 128. Water Pump
- 129. Coolant Recovery Tank
- 130. Coolant Fans/Clutches/Motors
- 131. Coolant Hoses
- 132. Wiring
- 133. Starter Operation
- 134. Ignition Operation
- 135. Battery
- 136. Alternator
- 137. Air Filter
- 138. Fuel System Operation

Road Test

- 139. Starting
- 140. Idling
- 141. Engine Noise
- 142. Throttle
- 143. Transmission Shift
- 144. Clutch Operation
- 145. Accelerating
- 146. Steering Alignment
- 147. Power Steering
- 148. Cruise Control
- 149. Braking
- 150. ABS (Anti-Lock Braking System)
- 151. Body/Suspension

Additional Notes

152. Additional Notes:



Comments

- 88. Left Front Tire 7/32 1422
- 89. Left Rear Tire 6/32 2421
- 90. Right Rear Tire 6/32 2421
- 91. Right Front Tire 7/32 2421
- 114. Brake Pads Front pads 70%
Rear pads 70%
- 116. Engine Oil Last service completed 05/2026 (carfax)