# Inspection Information

**Inspection Date:** 2026-11-05 **Inspection Location:** Los Angeles, CA **Client Name:** Motorenn Inc
**Client Phone:** 424-363-7410 **Client Email:** service@motorenn.com
**Client Address:** 5255 W 102nd Street **Seller:** Motorenn Inc
**Year:** 2022 **Make:** Ferrari **Model:** F8
**Mileage:** 9350 **VIN:** ZFF93LMA0N0277646 **Body Style:** Convertible
**Transmission:** Automatic **Engine:** 8 cylinder **Drive Type:** RWD
**Inspector:** Ryann Derrama **Inspector Phone:** **Inspector Email:**
**Interior Color:** Black **Exterior Color:** Red

G = Good F = Fair P = Poor

## Interior

| G | F | P | |
|---|---|---|---|
| ☑ | ☐ | ☐ | 1. Fuel Door Release |
| ☑ | ☐ | ☐ | 2. Hood Release |
| ☑ | ☐ | ☐ | 3. Trunk Lid Release |
| ☑ | ☐ | ☐ | 4. Air Bags |
| ☑ | ☐ | ☐ | 5. Tilt/Telescoping Steering Wheel |
| ☑ | ☐ | ☐ | 6. Steering Wheel Controls |
| ☑ | ☐ | ☐ | 7. Horn |
| ☑ | ☐ | ☐ | 8. Windshield Wiper Operation/Controls |
| ☑ | ☐ | ☐ | 9. Windshield Washer Operation/Controls |
| ☑ | ☐ | ☐ | 10. Instrument Panel |
| ☑ | ☐ | ☐ | 11. Warning Lights |
| ☑ | ☐ | ☐ | 12. Warning Chimes |
| ☑ | ☐ | ☐ | 13. Air Conditioning |
| ☑ | ☐ | ☐ | 14. Heating System |
| ☑ | ☐ | ☐ | 15. Defogger/Defroster |
| ☑ | ☐ | ☐ | 16. Clock |
| ☑ | ☐ | ☐ | 17. Radio |
| ☑ | ☐ | ☐ | 18. Audio Player |
| ☑ | ☐ | ☐ | 19. Speakers |
| ☑ | ☐ | ☐ | 20. Lighter/Power Outlet(s) |
| ☑ | ☐ | ☐ | 21. Interior Courtesy/Map/Dome Light |
| ☑ | ☐ | ☐ | 22. Glove Box |
| ☑ | ☐ | ☐ | 23. Glove Box Light |
| ☑ | ☐ | ☐ | 24. Center Console |
| ☑ | ☐ | ☐ | 25. Sun Visors |
| ☑ | ☐ | ☐ | 26. Sun Visors Lights |
| ☑ | ☐ | ☐ | 27. Vanity Mirrors |
| ☑ | ☐ | ☐ | 28. Inside Rear View Mirror |
| ☑ | ☐ | ☐ | 29. Armrests |

## Interior

| G | F | P | |
|---|---|---|---|
| ☑ | ☐ | ☐ | 30. Outside Mirror Operation/Controls |
| ☑ | ☐ | ☐ | 31. Door Locks Manual |
| ☑ | ☐ | ☐ | 32. Door Locks Automatic |
| ☑ | ☐ | ☐ | 33. Child Safety Locks |
| ☑ | ☐ | ☐ | 34. Window Controls |
| ☑ | ☐ | ☐ | 35. Door Handles |
| ☑ | ☐ | ☐ | 36. Heated/Cooled Seats |
| ☑ | ☐ | ☐ | 37. Seats |
| ☑ | ☐ | ☐ | 38. Seat Controls |
| ☑ | ☐ | ☐ | 39. Headrest |
| ☑ | ☐ | ☐ | 40. Seat Belts |
| ☐ | ☐ | ☐ | 41. Sunroof/Moonroof |
| ☑ | ☐ | ☐ | 42. Convertible Top |
| ☑ | ☐ | ☐ | 43. Headliner |
| ☑ | ☐ | ☐ | 44. Carpet |
| ☑ | ☐ | ☐ | 45. Floor Mats |
| ☑ | ☐ | ☐ | 46. Interior Trim |
| ☑ | ☐ | ☐ | 47. Door Panels |
| ☑ | ☐ | ☐ | 48. Luggage Compartment |
| ☑ | ☐ | ☐ | 49. Trunk Light |
| ☑ | ☐ | ☐ | 50. Jack and Tool Kit |

## Exterior

| G | F | P | |
|---|---|---|---|
| ☑ | ☐ | ☐ | 51. Windshield |
| ☑ | ☐ | ☐ | 52. Wiper Blades |
| ☑ | ☐ | ☐ | 53. Windows |
| ☑ | ☐ | ☐ | 54. Rear Window |
| ☑ | ☐ | ☐ | 55. Mirrors |
| ☑ | ☐ | ☐ | 56. Head Lights |
| ☑ | ☐ | ☐ | 57. High Beams |
| ☑ | ☐ | ☐ | 58. Parking Lights |
| ☑ | ☐ | ☐ | 59. Turn Signals |

## Exterior

| G | F | P | |
|---|---|---|---|
| ☑ | ☐ | ☐ | 60. Taillights |
| ☑ | ☐ | ☐ | 61. Brake Lights |
| ☑ | ☐ | ☐ | 62. Hazards |
| ☑ | ☐ | ☐ | 63. License Plate Lights |
| ☑ | ☐ | ☐ | 64. Reverse Lights |
| | | | 65. Fog Lights |
| ☑ | ☐ | ☐ | 66. Running Lights |
| ☑ | ☐ | ☐ | 67. Side Marker Lights |
| ☑ | ☐ | ☐ | 68. Body Panels |
| ☑ | ☐ | ☐ | 69. Front Bumper |
| ☑ | ☐ | ☐ | 70. Grille |
| ☑ | ☐ | ☐ | 71. Hood |
| ☑ | ☐ | ☐ | 72. Rear Bumper |
| ☑ | ☐ | ☐ | 73. Rear Hatch |
| ☑ | ☐ | ☐ | 74. Trunk |
| ☑ | ☐ | ☐ | 75. Left Front Fender |
| ☑ | ☐ | ☐ | 76. Left Front Door |
| ☑ | ☐ | ☐ | 77. Left Rear Fender |
| ☐ | ☐ | ☐ | 78. Left Rear Door |
| ☑ | ☐ | ☐ | 79. Right Rear Fender |
| ☐ | ☐ | ☐ | 80. Right Rear Door |
| ☑ | ☐ | ☐ | 81. Right Front Fender |
| ☑ | ☐ | ☐ | 82. Right Front Door |
| ☑ | ☐ | ☐ | 83. Roof |
| ☐ | ☐ | ☐ | 84. Roof Rack |
| ☑ | ☐ | ☐ | 85. Trim |
| ☑ | ☐ | ☐ | 86. Fuel Door |
| ☑ | ☐ | ☐ | 87. Paint |

## Tires

| G | F | P | |
|---|---|---|---|
| ☑ | ☐ | ☐ | 88. Left Front Tire |
| ☑ | ☐ | ☐ | 89. Left Rear Tire |
| ☑ | ☐ | ☐ | 90. Right Rear Tire |


© InspectARide.com

G F P

## Tires

- [x] [ ] [ ] 91. Right Front Tire
- [ ] [ ] [ ] 92. Spare Tire
- [x] [ ] [ ] 93. Wheels
- [x] [ ] [ ] 94. Wheel Lug Nuts

## Underbody

- [x] [ ] [ ] 95. Frame
- [x] [ ] [ ] 96. Overall Underbody Condition
- [x] [ ] [ ] 97. Exhaust System
- [x] [ ] [ ] 98. Catalytic Converter
- [x] [ ] [ ] 99. Transmission Mounts
- [x] [ ] [ ] 100. Transmission
- [x] [ ] [ ] 101. Differential/Drive Axle
- [x] [ ] [ ] 102. Universal Joints/CV Joints/Boots
- [x] [ ] [ ] 103. Power Steering
- [x] [ ] [ ] 104. Suspension
- [x] [ ] [ ] 105. Tie-Rods/Idler Arm
- [x] [ ] [ ] 106. Sway Bars
- [x] [ ] [ ] 107. Springs
- [x] [ ] [ ] 108. Shocks
- [x] [ ] [ ] 109. Control Arms
- [x] [ ] [ ] 110. Ball Joints/Bushings
- [x] [ ] [ ] 111. Rotors/Drums
- [x] [ ] [ ] 112. Calipers
- [x] [ ] [ ] 113. Parking Brake
- [x] [ ] [ ] 114. Brake Pads
- [x] [ ] [ ] 115. Brake Lines/Hoses/Fittings

## Underhood

- [x] [ ] [ ] 116. Engine Oil
- [x] [ ] [ ] 117. Brake Fluid
- [x] [ ] [ ] 118. Coolant
- [x] [ ] [ ] 119. Power Steering Fluid
- [x] [ ] [ ] 120. Transmission Fluid
- [x] [ ] [ ] 121. Washer Fluid
- [x] [ ] [ ] 122. Transfer Case Fluid
- [x] [ ] [ ] 123. Engine Mounts
- [x] [ ] [ ] 124. Overall Engine Condition

G F P

## Underhood

- [x] [ ] [ ] 125. Engine Belts
- [x] [ ] [ ] 126. Engine Hoses/Lines/Fittings
- [x] [ ] [ ] 127. Radiator
- [x] [ ] [ ] 128. Water Pump
- [x] [ ] [ ] 129. Coolant Recovery Tank
- [x] [ ] [ ] 130. Coolant Fans/Clutches/Motors
- [x] [ ] [ ] 131. Coolant Hoses
- [x] [ ] [ ] 132. Wiring
- [x] [ ] [ ] 133. Starter Operation
- [x] [ ] [ ] 134. Ignition Operation
- [x] [ ] [ ] 135. Battery
- [x] [ ] [ ] 136. Alternator
- [x] [ ] [ ] 137. Air Filter
- [x] [ ] [ ] 138. Fuel System Operation

## Road Test

- [x] [ ] [ ] 139. Starting
- [x] [ ] [ ] 140. Idling
- [x] [ ] [ ] 141. Engine Noise
- [x] [ ] [ ] 142. Throttle
- [x] [ ] [ ] 143. Transmission Shift
- [x] [ ] [ ] 144. Clutch Operation
- [x] [ ] [ ] 145. Accelerating
- [x] [ ] [ ] 146. Steering Alignment
- [x] [ ] [ ] 147. Power Steering
- [x] [ ] [ ] 148. Cruise Control
- [x] [ ] [ ] 149. Braking
- [x] [ ] [ ] 150. ABS (Anti-Lock Braking System)
- [x] [ ] [ ] 151. Body/Suspension

## Additional Notes

152. Additional Notes:



© InspectARide.com

## Comments

88. **Left Front Tire** 6/32 3323
89. **Left Rear Tire** 6/32 3125
90. **Right Rear Tire** 6/32 3125
91. **Right Front Tire** 6/32 3323
114. **Brake Pads** Front pads 70%
Rear pads 70%
116. **Engine Oil** Full service completed at Ferrari 10/2026
152. **Additional Notes:** Full body PPF


© InspectARide.com