Inspection Information

Inspection Date: 2026-09-09
Inspection Location: Los Angeles, CA
Client Name: Motorenn Inc
Client Phone: 424-363-7410
Client Email: service@motorenn.com
Client Address: 5255 W 102nd Street
Seller: Motorenn Inc
Year: 2023
Make: Aston Martin
Model: DBX
Mileage: 29168
VIN: SD7VUJBW8PTV05939
Body Style: SUV
Transmission: Automatic
Engine: 8 cylinder
Drive Type: AWD
Inspector: Ryann Derrama
Inspector Phone:
Inspector Email:
Interior Color: Tan
Exterior Color: Gray

G = Good F = Fair P = Poor

Interior

G	F	P	
☑	☐	☐	1. Fuel Door Release
☑	☐	☐	2. Hood Release
☑	☐	☐	3. Trunk Lid Release
☑	☐	☐	4. Air Bags
☑	☐	☐	5. Tilt/Telescoping Steering Wheel
☑	☐	☐	6. Steering Wheel Controls
☑	☐	☐	7. Horn
☑	☐	☐	8. Windshield Wiper Operation/Controls
☑	☐	☐	9. Windshield Washer Operation/Controls
☑	☐	☐	10. Instrument Panel
☑	☐	☐	11. Warning Lights
☑	☐	☐	12. Warning Chimes
☑	☐	☐	13. Air Conditioning
☑	☐	☐	14. Heating System
☑	☐	☐	15. Defogger/Defroster
☑	☐	☐	16. Clock
☑	☐	☐	17. Radio
☑	☐	☐	18. Audio Player
☑	☐	☐	19. Speakers
☑	☐	☐	20. Lighter/Power Outlet(s)
☑	☐	☐	21. Interior Courtesy/Map/Dome Light
☑	☐	☐	22. Glove Box
☑	☐	☐	23. Glove Box Light
☑	☐	☐	24. Center Console
☑	☐	☐	25. Sun Visors
☑	☐	☐	26. Sun Visors Lights
☑	☐	☐	27. Vanity Mirrors
☑	☐	☐	28. Inside Rear View Mirror
☑	☐	☐	29. Armrests

Interior

G	F	P	
☑	☐	☐	30. Outside Mirror Operation/Controls
☑	☐	☐	31. Door Locks Manual
☑	☐	☐	32. Door Locks Automatic
☑	☐	☐	33. Child Safety Locks
☑	☐	☐	34. Window Controls
☑	☐	☐	35. Door Handles
☑	☐	☐	36. Heated/Cooled Seats
☑	☐	☐	37. Seats
☑	☐	☐	38. Seat Controls
☑	☐	☐	39. Headrest
☑	☐	☐	40. Seat Belts
			41. Sunroof/Moonroof
			42. Convertible Top
☑	☐	☐	43. Headliner
☑	☐	☐	44. Carpet
☑	☐	☐	45. Floor Mats
☑	☐	☐	46. Interior Trim
☑	☐	☐	47. Door Panels
☑	☐	☐	48. Luggage Compartment
☑	☐	☐	49. Trunk Light
☑	☐	☐	50. Jack and Tool Kit

Exterior

G	F	P	
☑	☐	☐	51. Windshield
☑	☐	☐	52. Wiper Blades
☑	☐	☐	53. Windows
☑	☐	☐	54. Rear Window
☑	☐	☐	55. Mirrors
☑	☐	☐	56. Head Lights
☑	☐	☐	57. High Beams
☑	☐	☐	58. Parking Lights
☑	☐	☐	59. Turn Signals

Exterior

G	F	P	
☑	☐	☐	60. Taillights
☑	☐	☐	61. Brake Lights
☑	☐	☐	62. Hazards
☑	☐	☐	63. License Plate Lights
☑	☐	☐	64. Reverse Lights
☑	☐	☐	65. Fog Lights
☑	☐	☐	66. Running Lights
☑	☐	☐	67. Side Marker Lights
☑	☐	☐	68. Body Panels
☑	☐	☐	69. Front Bumper
☑	☐	☐	70. Grille
☑	☐	☐	71. Hood
☑	☐	☐	72. Rear Bumper
☑	☐	☐	73. Rear Hatch
☑	☐	☐	74. Trunk
☑	☐	☐	75. Left Front Fender
☑	☐	☐	76. Left Front Door
☑	☐	☐	77. Left Rear Fender
☑	☐	☐	78. Left Rear Door
☑	☐	☐	79. Right Rear Fender
☑	☐	☐	80. Right Rear Door
☑	☐	☐	81. Right Front Fender
☑	☐	☐	82. Right Front Door
☑	☐	☐	83. Roof
			84. Roof Rack
☑	☐	☐	85. Trim
☑	☐	☐	86. Fuel Door
☑	☐	☐	87. Paint

Tires

G	F	P	
☑	☐	☐	88. Left Front Tire
☑	☐	☐	89. Left Rear Tire
☑	☐	☐	90. Right Rear Tire

© InspectARide.com

G F P

Tires

- [x] [ ] [ ] 91. Right Front Tire
- [ ] [ ] [ ] 92. Spare Tire
- [x] [ ] [ ] 93. Wheels
- [x] [ ] [ ] 94. Wheel Lug Nuts

Underbody

- [x] [ ] [ ] 95. Frame
- [x] [ ] [ ] 96. Overall Underbody Condition
- [x] [ ] [ ] 97. Exhaust System
- [x] [ ] [ ] 98. Catalytic Converter
- [x] [ ] [ ] 99. Transmission Mounts
- [x] [ ] [ ] 100. Transmission
- [x] [ ] [ ] 101. Differential/Drive Axle
- [x] [ ] [ ] 102. Universal Joints/CV Joints/Boots
- [x] [ ] [ ] 103. Power Steering
- [x] [ ] [ ] 104. Suspension
- [x] [ ] [ ] 105. Tie-Rods/Idler Arm
- [x] [ ] [ ] 106. Sway Bars
- [x] [ ] [ ] 107. Springs
- [x] [ ] [ ] 108. Shocks
- [x] [ ] [ ] 109. Control Arms
- [x] [ ] [ ] 110. Ball Joints/Bushings
- [x] [ ] [ ] 111. Rotors/Drums
- [x] [ ] [ ] 112. Calipers
- [x] [ ] [ ] 113. Parking Brake
- [x] [ ] [ ] 114. Brake Pads
- [x] [ ] [ ] 115. Brake Lines/Hoses/Fittings

Underhood

- [x] [ ] [ ] 116. Engine Oil
- [x] [ ] [ ] 117. Brake Fluid
- [x] [ ] [ ] 118. Coolant
- [x] [ ] [ ] 119. Power Steering Fluid
- [x] [ ] [ ] 120. Transmission Fluid
- [x] [ ] [ ] 121. Washer Fluid
- [x] [ ] [ ] 122. Transfer Case Fluid
- [x] [ ] [ ] 123. Engine Mounts
- [x] [ ] [ ] 124. Overall Engine Condition

G F P

Underhood

- [x] [ ] [ ] 125. Engine Belts
- [x] [ ] [ ] 126. Engine Hoses/Lines/Fittings
- [x] [ ] [ ] 127. Radiator
- [x] [ ] [ ] 128. Water Pump
- [x] [ ] [ ] 129. Coolant Recovery Tank
- [x] [ ] [ ] 130. Coolant Fans/Clutches/Motors
- [x] [ ] [ ] 131. Coolant Hoses
- [x] [ ] [ ] 132. Wiring
- [x] [ ] [ ] 133. Starter Operation
- [x] [ ] [ ] 134. Ignition Operation
- [x] [ ] [ ] 135. Battery
- [x] [ ] [ ] 136. Alternator
- [x] [ ] [ ] 137. Air Filter
- [x] [ ] [ ] 138. Fuel System Operation

Road Test

- [x] [ ] [ ] 139. Starting
- [x] [ ] [ ] 140. Idling
- [x] [ ] [ ] 141. Engine Noise
- [x] [ ] [ ] 142. Throttle
- [x] [ ] [ ] 143. Transmission Shift
- [x] [ ] [ ] 144. Clutch Operation
- [x] [ ] [ ] 145. Accelerating
- [x] [ ] [ ] 146. Steering Alignment
- [x] [ ] [ ] 147. Power Steering
- [x] [ ] [ ] 148. Cruise Control
- [x] [ ] [ ] 149. Braking
- [x] [ ] [ ] 150. ABS (Anti-Lock Braking System)
- [x] [ ] [ ] 151. Body/Suspension

Additional Notes

152. Additional Notes:

© InspectARide.com

Comments

88. **Left Front Tire** 8/32 2825 brand new
89. **Left Rear Tire** 6/32 1524
90. **Right Rear Tire** 6/32 1824
91. **Right Front Tire** 8/32 3825 brand new
114. **Brake Pads** Front pads 70%
Rear pads 70%
116. **Engine Oil** Next service due 03/2027

© InspectARide.com