



Inspection Information

Inspection Date: 2026-03-17	Inspection Location: Los Angeles, CA	Client Name: Motorenn Inc
Client Phone: 424-363-7410	Client Email: service@motorenn.com	
Client Address: 5255 W 102nd Street		Seller: Motorenn Inc
Year: 2024	Make: Bentley	Model: Flying Spur
Mileage: 5771	VIN: SCBBB6ZG2RC016219	Body Style: Sedan
Transmission: Automatic	Engine: 12 cylinder	Drive Type: RWD
Inspector: Ryann Derrama	Inspector Phone:	Inspector Email:
Interior Color: Red	Exterior Color: White	

G = Good F = Fair P = Poor

G F P

Interior

- ☒☐☐
1. Fuel Door Release
- ☒☐☐
2. Hood Release
- ☒☐☐
3. Trunk Lid Release
- ☒☐☐
4. Air Bags
- ☒☐☐
5. Tilt/Telescoping Steering Wheel
- ☒☐☐
6. Steering Wheel Controls
- ☒☐☐
7. Horn
- ☒☐☐
8. Windshield Wiper Operation/Controls
- ☒☐☐
9. Windshield Washer Operation/Controls
- ☒☐☐
10. Instrument Panel
- ☒☐☐
11. Warning Lights
- ☒☐☐
12. Warning Chimes
- ☒☐☐
13. Air Conditioning
- ☒☐☐
14. Heating System
- ☒☐☐
15. Defogger/Defroster
- ☒☐☐
16. Clock
- ☒☐☐
17. Radio
- ☒☐☐
18. Audio Player
- ☒☐☐
19. Speakers
- ☒☐☐
20. Lighter/Power Outlet(s)
- ☒☐☐
21. Interior Courtesy/Map/Dome Light
- ☒☐☐
22. Glove Box
- ☒☐☐
23. Glove Box Light
- ☒☐☐
24. Center Console
- ☒☐☐
25. Sun Visors
- ☒☐☐
26. Sun Visors Lights
- ☒☐☐
27. Vanity Mirrors
- ☒☐☐
28. Inside Rear View Mirror
- ☒☐☐
29. Armrests

G F P

Interior

- ☒☐☐
30. Outside Mirror Operation/Controls
- ☒☐☐
31. Door Locks Manual
- ☒☐☐
32. Door Locks Automatic
- ☒☐☐
33. Child Safety Locks
- ☒☐☐
34. Window Controls
- ☒☐☐
35. Door Handles
- ☒☐☐
36. Heated/Cooled Seats
- ☒☐☐
37. Seats
- ☒☐☐
38. Seat Controls
- ☒☐☐
39. Headrest
- ☒☐☐
40. Seat Belts
- ☒☐☐
41. Sunroof/Moonroof
- ☒☐☐
42. Convertible Top
- ☒☐☐
43. Headliner
- ☒☐☐
44. Carpet
- ☒☐☐
45. Floor Mats
- ☒☐☐
46. Interior Trim
- ☒☐☐
47. Door Panels
- ☒☐☐
48. Luggage Compartment
- ☒☐☐
49. Trunk Light
- ☒☐☐
50. Jack and Tool Kit

G F P

Exterior

- ☒☐☐
60. Taillights
- ☒☐☐
61. Brake Lights
- ☒☐☐
62. Hazards
- ☒☐☐
63. License Plate Lights
- ☒☐☐
64. Reverse Lights
- ☒☐☐
65. Fog Lights
- ☒☐☐
66. Running Lights
- ☒☐☐
67. Side Marker Lights
- ☒☐☐
68. Body Panels
- ☒☐☐
69. Front Bumper
- ☒☐☐
70. Grille
- ☒☐☐
71. Hood
- ☒☐☐
72. Rear Bumper
- ☒☐☐
73. Rear Hatch
- ☒☐☐
74. Trunk
- ☒☐☐
75. Left Front Fender
- ☒☐☐
76. Left Front Door
- ☒☐☐
77. Left Rear Fender
- ☒☐☐
78. Left Rear Door
- ☒☐☐
79. Right Rear Fender
- ☒☐☐
80. Right Rear Door
- ☒☐☐
81. Right Front Fender
- ☒☐☐
82. Right Front Door
- ☒☐☐
83. Roof
- ☒☐☐
84. Roof Rack
- ☒☐☐
85. Trim
- ☒☐☐
86. Fuel Door
- ☒☐☐
87. Paint

Tires

- ☒☐☐
88. Left Front Tire
- ☒☐☐
89. Left Rear Tire
- ☒☐☐
90. Right Rear Tire



G F P

Tires

- | | | | |
|-------------------------------------|--------------------------|--------------------------|----------------------|
| ☒ | ☐ | ☐ | 91. Right Front Tire |
| ☐ | ☐ | ☐ | 92. Spare Tire |
| ☒ | ☐ | ☐ | 93. Wheels |
| ☒ | ☐ | ☐ | 94. Wheel Lug Nuts |

Underbody

- | | | | |
|-------------------------------------|--------------------------|--------------------------|---------------------------------------|
| ☒ | ☐ | ☐ | 95. Frame |
| ☒ | ☐ | ☐ | 96. Overall Underbody Condition |
| ☒ | ☐ | ☐ | 97. Exhaust System |
| ☒ | ☐ | ☐ | 98. Catalytic Converter |
| ☒ | ☐ | ☐ | 99. Transmission Mounts |
| ☒ | ☐ | ☐ | 100. Transmission |
| ☒ | ☐ | ☐ | 101. Differential/Drive Axle |
| ☒ | ☐ | ☐ | 102. Universal Joints/CV Joints/Boots |
| ☒ | ☐ | ☐ | 103. Power Steering |
| ☒ | ☐ | ☐ | 104. Suspension |
| ☒ | ☐ | ☐ | 105. Tie-Rods/Idler Arm |
| ☒ | ☐ | ☐ | 106. Sway Bars |
| ☒ | ☐ | ☐ | 107. Springs |
| ☒ | ☐ | ☐ | 108. Shocks |
| ☒ | ☐ | ☐ | 109. Control Arms |
| ☒ | ☐ | ☐ | 110. Ball Joints/Bushings |
| ☒ | ☐ | ☐ | 111. Rotors/Drums |
| ☒ | ☐ | ☐ | 112. Calipers |
| ☒ | ☐ | ☐ | 113. Parking Brake |
| ☒ | ☐ | ☐ | 114. Brake Pads |
| ☒ | ☐ | ☐ | 115. Brake Lines/Hoses/Fittings |

Underhood

- | | | | |
|-------------------------------------|--------------------------|--------------------------|-------------------------------|
| ☒ | ☐ | ☐ | 116. Engine Oil |
| ☒ | ☐ | ☐ | 117. Brake Fluid |
| ☒ | ☐ | ☐ | 118. Coolant |
| ☒ | ☐ | ☐ | 119. Power Steering Fluid |
| ☒ | ☐ | ☐ | 120. Transmission Fluid |
| ☒ | ☐ | ☐ | 121. Washer Fluid |
| ☒ | ☐ | ☐ | 122. Transfer Case Fluid |
| ☒ | ☐ | ☐ | 123. Engine Mounts |
| ☒ | ☐ | ☐ | 124. Overall Engine Condition |

G F P

Underhood

- | | | | |
|-------------------------------------|--------------------------|--------------------------|-----------------------------------|
| ☒ | ☐ | ☐ | 125. Engine Belts |
| ☒ | ☐ | ☐ | 126. Engine Hoses/Lines/Fittings |
| ☒ | ☐ | ☐ | 127. Radiator |
| ☒ | ☐ | ☐ | 128. Water Pump |
| ☒ | ☐ | ☐ | 129. Coolant Recovery Tank |
| ☒ | ☐ | ☐ | 130. Coolant Fans/Clutches/Motors |
| ☒ | ☐ | ☐ | 131. Coolant Hoses |
| ☒ | ☐ | ☐ | 132. Wiring |
| ☒ | ☐ | ☐ | 133. Starter Operation |
| ☒ | ☐ | ☐ | 134. Ignition Operation |
| ☒ | ☐ | ☐ | 135. Battery |
| ☒ | ☐ | ☐ | 136. Alternator |
| ☒ | ☐ | ☐ | 137. Air Filter |
| ☒ | ☐ | ☐ | 138. Fuel System Operation |

Road Test

- | | | | |
|-------------------------------------|--------------------------|--------------------------|-------------------------------------|
| ☒ | ☐ | ☐ | 139. Starting |
| ☒ | ☐ | ☐ | 140. Idling |
| ☒ | ☐ | ☐ | 141. Engine Noise |
| ☒ | ☐ | ☐ | 142. Throttle |
| ☒ | ☐ | ☐ | 143. Transmission Shift |
| ☒ | ☐ | ☐ | 144. Clutch Operation |
| ☒ | ☐ | ☐ | 145. Accelerating |
| ☒ | ☐ | ☐ | 146. Steering Alignment |
| ☒ | ☐ | ☐ | 147. Power Steering |
| ☒ | ☐ | ☐ | 148. Cruise Control |
| ☒ | ☐ | ☐ | 149. Braking |
| ☒ | ☐ | ☐ | 150. ABS (Anti-Lock Braking System) |
| ☒ | ☐ | ☐ | 151. Body/Suspension |

Additional Notes

152. Additional Notes:



Comments

- 88. Left Front Tire 6/32 5323
- 89. Left Rear Tire 5/32 0824
- 90. Right Rear Tire 5/32 0224
- 91. Right Front Tire 6/32 0124
- 114. Brake Pads Front pads 70%
Rear pads 70%
- 116. Engine Oil Service completed 10/2025 (carfax)