Inspection Information

Inspection Date: 2025-11-24
Inspection Location: Los Angeles, CA
Client Name: Motorenn Inc
Client Phone: 424-363-7410
Client Email: service@motorenn.com
Client Address: 5255 W 102nd Street
Seller: Motorenn Inc
Year: 2024
Make: Chevrolet
Model: Corvette
Mileage: 14754
VIN: 1G1YF2D34R5608968
Body Style: Coupe
Transmission: Automatic
Engine: 8 cylinder
Drive Type: RWD
Inspector: Ryann Derrama
Inspector Phone:
Inspector Email:
Interior Color: Blue
Exterior Color: Gray

G = Good F = Fair P = Poor

Interior

G	F	P		
✓			1.	Fuel Door Release
✓			2.	Hood Release
✓			3.	Trunk Lid Release
✓			4.	Air Bags
✓			5.	Tilt/Telescoping Steering Wheel
✓			6.	Steering Wheel Controls
✓			7.	Horn
✓			8.	Windshield Wiper Operation/Controls
✓			9.	Windshield Washer Operation/Controls
✓			10.	Instrument Panel
✓			11.	Warning Lights
✓			12.	Warning Chimes
✓			13.	Air Conditioning
✓			14.	Heating System
✓			15.	Defogger/Defroster
✓			16.	Clock
✓			17.	Radio
✓			18.	Audio Player
✓			19.	Speakers
✓			20.	Lighter/Power Outlet(s)
✓			21.	Interior Courtesy/Map/Dome Light
✓			22.	Glove Box
✓			23.	Glove Box Light
✓			24.	Center Console
✓			25.	Sun Visors
✓			26.	Sun Visors Lights
✓			27.	Vanity Mirrors
✓			28.	Inside Rear View Mirror
✓			29.	Armrests

Interior

G	F	P		
✓			30.	Outside Mirror Operation/Controls
✓			31.	Door Locks Manual
✓			32.	Door Locks Automatic
✓			33.	Child Safety Locks
✓			34.	Window Controls
✓			35.	Door Handles
✓			36.	Heated/Cooled Seats
✓			37.	Seats
✓			38.	Seat Controls
✓			39.	Headrest
✓			40.	Seat Belts
			41.	Sunroof/Moonroof
			42.	Convertible Top
✓			43.	Headliner
✓			44.	Carpet
✓			45.	Floor Mats
✓			46.	Interior Trim
✓			47.	Door Panels
✓			48.	Luggage Compartment
✓			49.	Trunk Light
✓			50.	Jack and Tool Kit

Exterior

G	F	P		
✓			51.	Windshield
✓			52.	Wiper Blades
✓			53.	Windows
✓			54.	Rear Window
✓			55.	Mirrors
✓			56.	Head Lights
✓			57.	High Beams
✓			58.	Parking Lights
✓			59.	Turn Signals

Exterior

G	F	P		
✓			60.	Taillights
✓			61.	Brake Lights
✓			62.	Hazards
✓			63.	License Plate Lights
✓			64.	Reverse Lights
✓			65.	Fog Lights
✓			66.	Running Lights
✓			67.	Side Marker Lights
✓			68.	Body Panels
✓			69.	Front Bumper
✓			70.	Grille
✓			71.	Hood
✓			72.	Rear Bumper
✓			73.	Rear Hatch
✓			74.	Trunk
✓			75.	Left Front Fender
✓			76.	Left Front Door
✓			77.	Left Rear Fender
			78.	Left Rear Door
✓			79.	Right Rear Fender
			80.	Right Rear Door
✓			81.	Right Front Fender
✓			82.	Right Front Door
✓			83.	Roof
			84.	Roof Rack
✓			85.	Trim
✓			86.	Fuel Door
✓			87.	Paint

Tires

G	F	P		
	✓		88.	Left Front Tire
	✓		89.	Left Rear Tire
	✓		90.	Right Rear Tire

© InspectARide.com

G F P

Tires

- [ ] [x] [ ] 91. Right Front Tire
- [ ] [ ] [ ] 92. Spare Tire
- [x] [ ] [ ] 93. Wheels
- [x] [ ] [ ] 94. Wheel Lug Nuts

Underbody

- [x] [ ] [ ] 95. Frame
- [x] [ ] [ ] 96. Overall Underbody Condition
- [x] [ ] [ ] 97. Exhaust System
- [x] [ ] [ ] 98. Catalytic Converter
- [x] [ ] [ ] 99. Transmission Mounts
- [x] [ ] [ ] 100. Transmission
- [x] [ ] [ ] 101. Differential/Drive Axle
- [x] [ ] [ ] 102. Universal Joints/CV Joints/Boots
- [x] [ ] [ ] 103. Power Steering
- [x] [ ] [ ] 104. Suspension
- [x] [ ] [ ] 105. Tie-Rods/Idler Arm
- [x] [ ] [ ] 106. Sway Bars
- [x] [ ] [ ] 107. Springs
- [x] [ ] [ ] 108. Shocks
- [x] [ ] [ ] 109. Control Arms
- [x] [ ] [ ] 110. Ball Joints/Bushings
- [x] [ ] [ ] 111. Rotors/Drums
- [x] [ ] [ ] 112. Calipers
- [x] [ ] [ ] 113. Parking Brake
- [x] [ ] [ ] 114. Brake Pads
- [x] [ ] [ ] 115. Brake Lines/Hoses/Fittings

Underhood

- [x] [ ] [ ] 116. Engine Oil
- [x] [ ] [ ] 117. Brake Fluid
- [x] [ ] [ ] 118. Coolant
- [x] [ ] [ ] 119. Power Steering Fluid
- [x] [ ] [ ] 120. Transmission Fluid
- [x] [ ] [ ] 121. Washer Fluid
- [x] [ ] [ ] 122. Transfer Case Fluid
- [x] [ ] [ ] 123. Engine Mounts
- [x] [ ] [ ] 124. Overall Engine Condition

G F P

Underhood

- [x] [ ] [ ] 125. Engine Belts
- [x] [ ] [ ] 126. Engine Hoses/Lines/Fittings
- [x] [ ] [ ] 127. Radiator
- [x] [ ] [ ] 128. Water Pump
- [x] [ ] [ ] 129. Coolant Recovery Tank
- [x] [ ] [ ] 130. Coolant Fans/Clutches/Motors
- [x] [ ] [ ] 131. Coolant Hoses
- [x] [ ] [ ] 132. Wiring
- [x] [ ] [ ] 133. Starter Operation
- [x] [ ] [ ] 134. Ignition Operation
- [x] [ ] [ ] 135. Battery
- [x] [ ] [ ] 136. Alternator
- [x] [ ] [ ] 137. Air Filter
- [x] [ ] [ ] 138. Fuel System Operation

Road Test

- [x] [ ] [ ] 139. Starting
- [x] [ ] [ ] 140. Idling
- [x] [ ] [ ] 141. Engine Noise
- [x] [ ] [ ] 142. Throttle
- [x] [ ] [ ] 143. Transmission Shift
- [x] [ ] [ ] 144. Clutch Operation
- [x] [ ] [ ] 145. Accelerating
- [x] [ ] [ ] 146. Steering Alignment
- [x] [ ] [ ] 147. Power Steering
- [x] [ ] [ ] 148. Cruise Control
- [x] [ ] [ ] 149. Braking
- [x] [ ] [ ] 150. ABS (Anti-Lock Braking System)
- [x] [ ] [ ] 151. Body/Suspension

Additional Notes

152. Additional Notes:

© InspectARide.com

Comments

88. **Left Front Tire** 4/32 4524
89. **Left Rear Tire** 3/32 4023
90. **Right Rear Tire** 3/32 4523
91. **Right Front Tire** 4/32 4524
114. **Brake Pads** Front pads 80%
Rear pads 80%

116. **Engine Oil** Full service completed 11/2025
152. **Additional Notes:** Full body PPF

© InspectARide.com