



Inspection Information

|                                            |                                             |                                  |
|--------------------------------------------|---------------------------------------------|----------------------------------|
| <b>Inspection Date:</b> 2026-06-23         | <b>Inspection Location:</b> Los Angeles, CA | <b>Client Name:</b> Motorenn Inc |
| <b>Client Phone:</b> 424-363-7410          | <b>Client Email:</b> service@motorenn.com   |                                  |
| <b>Client Address:</b> 5255 W 102nd Street |                                             | <b>Seller:</b> Motorenn Inc      |
| <b>Year:</b> 2024                          | <b>Make:</b> Mercedes-Benz                  | <b>Model:</b> G-Class            |
| <b>Mileage:</b> 10745                      | <b>VIN:</b> W1NYC8AJ0RX492610               | <b>Body Style:</b> SUV           |
| <b>Transmission:</b> Automatic             | <b>Engine:</b> 8 cylinder                   | <b>Drive Type:</b> 4WD           |
| <b>Inspector:</b> Ryann Derrama            | <b>Inspector Phone:</b>                     | <b>Inspector Email:</b>          |
| <b>Interior Color:</b> Black               | <b>Exterior Color:</b> Black                |                                  |

G = Good F = Fair P = Poor

G F P

Interior

- ☒☐☐
1. Fuel Door Release
- ☒☐☐
2. Hood Release
- ☒☐☐
3. Trunk Lid Release
- ☒☐☐
4. Air Bags
- ☒☐☐
5. Tilt/Telescoping Steering Wheel
- ☒☐☐
6. Steering Wheel Controls
- ☒☐☐
7. Horn
- ☒☐☐
8. Windshield Wiper Operation/Controls
- ☒☐☐
9. Windshield Washer Operation/Controls
- ☒☐☐
10. Instrument Panel
- ☒☐☐
11. Warning Lights
- ☒☐☐
12. Warning Chimes
- ☒☐☐
13. Air Conditioning
- ☒☐☐
14. Heating System
- ☒☐☐
15. Defogger/Defroster
- ☒☐☐
16. Clock
- ☒☐☐
17. Radio
- ☒☐☐
18. Audio Player
- ☒☐☐
19. Speakers
- ☒☐☐
20. Lighter/Power Outlet(s)
- ☒☐☐
21. Interior Courtesy/Map/Dome Light
- ☒☐☐
22. Glove Box
- ☒☐☐
23. Glove Box Light
- ☒☐☐
24. Center Console
- ☒☐☐
25. Sun Visors
- ☒☐☐
26. Sun Visors Lights
- ☒☐☐
27. Vanity Mirrors
- ☒☐☐
28. Inside Rear View Mirror
- ☒☐☐
29. Armrests

G F P

Interior

- ☒☐☐
30. Outside Mirror Operation/Controls
- ☒☐☐
31. Door Locks Manual
- ☒☐☐
32. Door Locks Automatic
- ☒☐☐
33. Child Safety Locks
- ☒☐☐
34. Window Controls
- ☒☐☐
35. Door Handles
- ☒☐☐
36. Heated/Cooled Seats
- ☒☐☐
37. Seats
- ☒☐☐
38. Seat Controls
- ☒☐☐
39. Headrest
- ☒☐☐
40. Seat Belts
- ☒☐☐
41. Sunroof/Moonroof
- ☒☐☐
42. Convertible Top
- ☒☐☐
43. Headliner
- ☒☐☐
44. Carpet
- ☒☐☐
45. Floor Mats
- ☒☐☐
46. Interior Trim
- ☒☐☐
47. Door Panels
- ☒☐☐
48. Luggage Compartment
- ☒☐☐
49. Trunk Light
- ☒☐☐
50. Jack and Tool Kit

Exterior

- ☒☐☐
51. Windshield
- ☒☐☐
52. Wiper Blades
- ☒☐☐
53. Windows
- ☒☐☐
54. Rear Window
- ☒☐☐
55. Mirrors
- ☒☐☐
56. Head Lights
- ☒☐☐
57. High Beams
- ☒☐☐
58. Parking Lights
- ☒☐☐
59. Turn Signals

G F P

Exterior

- ☒☐☐
60. Taillights
- ☒☐☐
61. Brake Lights
- ☒☐☐
62. Hazards
- ☒☐☐
63. License Plate Lights
- ☒☐☐
64. Reverse Lights
- ☒☐☐
65. Fog Lights
- ☒☐☐
66. Running Lights
- ☒☐☐
67. Side Marker Lights
- ☒☐☐
68. Body Panels
- ☒☐☐
69. Front Bumper
- ☒☐☐
70. Grille
- ☒☐☐
71. Hood
- ☒☐☐
72. Rear Bumper
- ☒☐☐
73. Rear Hatch
- ☒☐☐
74. Trunk
- ☒☐☐
75. Left Front Fender
- ☒☐☐
76. Left Front Door
- ☒☐☐
77. Left Rear Fender
- ☒☐☐
78. Left Rear Door
- ☒☐☐
79. Right Rear Fender
- ☒☐☐
80. Right Rear Door
- ☒☐☐
81. Right Front Fender
- ☒☐☐
82. Right Front Door
- ☒☐☐
83. Roof
- ☒☐☐
84. Roof Rack
- ☒☐☐
85. Trim
- ☒☐☐
86. Fuel Door
- ☒☐☐
87. Paint

Tires

- ☒☐☐
88. Left Front Tire
- ☒☐☐
89. Left Rear Tire
- ☒☐☐
90. Right Rear Tire



G F P

Tires

- ☒

☐

☐
91. Right Front Tire

☒

☐

☐

☒

☐

☐

☒

☐

☐

Underbody

- ☒

☐

☐
95. Frame

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

Underhood

- ☒

☐

☐
116. Engine Oil

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

G F P

Underhood

- ☒

☐

☐
125. Engine Belts

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

Road Test

- ☒

☐

☐
139. Starting

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

☒

☐

☐

Additional Notes

152. Additional Notes:



---

Comments

- 88. Left Front Tire 90% tread 0123
- 89. Left Rear Tire 90% tread 0223
- 90. Right Rear Tire 90% tread 0423
- 91. Right Front Tire 90% tread 5222
- 114. Brake Pads Front Pads 70%  
Rear Pads 80%
- 116. Engine Oil Last service 01/2026 (carfax)