



Inspection Information

Inspection Date: 2026-08-10	Inspection Location: Los Angeles, CA	Client Name: Motorenn Inc
Client Phone: 424-363-7410	Client Email: service@motorenn.com	
Client Address: 5255 W 102nd Street		Seller: Motorenn Inc
Year: 2025	Make: Mercedes-Benz	Model: G-Class
Mileage: 7753	VIN: W1NWH5AB6SX021471	Body Style: SUV
Transmission: Automatic	Engine: 8 cylinder	Drive Type: AWD
Inspector: Ryann Derrama	Inspector Phone:	Inspector Email:
Interior Color: Black	Exterior Color: Gray	

G = Good F = Fair P = Poor

G F P			G F P			G F P		
Interior			Interior			Exterior		
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐				☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐
☒	☐	☐	☒	☐	☐	☒	☐	☐



G F P

Tires

- | | | | |
|-------------------------------------|--------------------------|--------------------------|----------------------|
| ☒ | ☐ | ☐ | 91. Right Front Tire |
| ☒ | ☐ | ☐ | 92. Spare Tire |
| ☒ | ☐ | ☐ | 93. Wheels |
| ☒ | ☐ | ☐ | 94. Wheel Lug Nuts |

Underbody

- | | | | |
|-------------------------------------|--------------------------|--------------------------|---------------------------------------|
| ☒ | ☐ | ☐ | 95. Frame |
| ☒ | ☐ | ☐ | 96. Overall Underbody Condition |
| ☒ | ☐ | ☐ | 97. Exhaust System |
| ☒ | ☐ | ☐ | 98. Catalytic Converter |
| ☒ | ☐ | ☐ | 99. Transmission Mounts |
| ☒ | ☐ | ☐ | 100. Transmission |
| ☒ | ☐ | ☐ | 101. Differential/Drive Axle |
| ☒ | ☐ | ☐ | 102. Universal Joints/CV Joints/Boots |
| ☒ | ☐ | ☐ | 103. Power Steering |
| ☒ | ☐ | ☐ | 104. Suspension |
| ☒ | ☐ | ☐ | 105. Tie-Rods/Idler Arm |
| ☒ | ☐ | ☐ | 106. Sway Bars |
| ☒ | ☐ | ☐ | 107. Springs |
| ☒ | ☐ | ☐ | 108. Shocks |
| ☒ | ☐ | ☐ | 109. Control Arms |
| ☒ | ☐ | ☐ | 110. Ball Joints/Bushings |
| ☒ | ☐ | ☐ | 111. Rotors/Drums |
| ☒ | ☐ | ☐ | 112. Calipers |
| ☒ | ☐ | ☐ | 113. Parking Brake |
| ☒ | ☐ | ☐ | 114. Brake Pads |
| ☒ | ☐ | ☐ | 115. Brake Lines/Hoses/Fittings |

Underhood

- | | | | |
|-------------------------------------|--------------------------|--------------------------|-------------------------------|
| ☒ | ☐ | ☐ | 116. Engine Oil |
| ☒ | ☐ | ☐ | 117. Brake Fluid |
| ☒ | ☐ | ☐ | 118. Coolant |
| ☒ | ☐ | ☐ | 119. Power Steering Fluid |
| ☒ | ☐ | ☐ | 120. Transmission Fluid |
| ☒ | ☐ | ☐ | 121. Washer Fluid |
| ☒ | ☐ | ☐ | 122. Transfer Case Fluid |
| ☒ | ☐ | ☐ | 123. Engine Mounts |
| ☒ | ☐ | ☐ | 124. Overall Engine Condition |

G F P

Underhood

- | | | | |
|-------------------------------------|--------------------------|--------------------------|-----------------------------------|
| ☒ | ☐ | ☐ | 125. Engine Belts |
| ☒ | ☐ | ☐ | 126. Engine Hoses/Lines/Fittings |
| ☒ | ☐ | ☐ | 127. Radiator |
| ☒ | ☐ | ☐ | 128. Water Pump |
| ☒ | ☐ | ☐ | 129. Coolant Recovery Tank |
| ☒ | ☐ | ☐ | 130. Coolant Fans/Clutches/Motors |
| ☒ | ☐ | ☐ | 131. Coolant Hoses |
| ☒ | ☐ | ☐ | 132. Wiring |
| ☒ | ☐ | ☐ | 133. Starter Operation |
| ☒ | ☐ | ☐ | 134. Ignition Operation |
| ☒ | ☐ | ☐ | 135. Battery |
| ☒ | ☐ | ☐ | 136. Alternator |
| ☒ | ☐ | ☐ | 137. Air Filter |
| ☒ | ☐ | ☐ | 138. Fuel System Operation |

Road Test

- | | | | |
|-------------------------------------|--------------------------|--------------------------|-------------------------------------|
| ☒ | ☐ | ☐ | 139. Starting |
| ☒ | ☐ | ☐ | 140. Idling |
| ☒ | ☐ | ☐ | 141. Engine Noise |
| ☒ | ☐ | ☐ | 142. Throttle |
| ☒ | ☐ | ☐ | 143. Transmission Shift |
| ☒ | ☐ | ☐ | 144. Clutch Operation |
| ☒ | ☐ | ☐ | 145. Accelerating |
| ☒ | ☐ | ☐ | 146. Steering Alignment |
| ☒ | ☐ | ☐ | 147. Power Steering |
| ☒ | ☐ | ☐ | 148. Cruise Control |
| ☒ | ☐ | ☐ | 149. Braking |
| ☒ | ☐ | ☐ | 150. ABS (Anti-Lock Braking System) |
| ☒ | ☐ | ☐ | 151. Body/Suspension |

Additional Notes

152. Additional Notes:



Comments

- 88. Left Front Tire 7/32 3424
- 89. Left Rear Tire 8/32 3424
- 90. Right Rear Tire 8/32 3324
- 91. Right Front Tire 7/32 3324
- 114. Brake Pads Front Pads 70%
Rear Pads 70%
- 116. Engine Oil Next service due 02/27