



Inspection Information

Inspection Date: 2026-08-03**Client Phone:** (424) 363-7410**Client Address:** 5255 W 102nd Street**Year:** 2026**Mileage:** 748**Transmission:** Standard**Inspector:** Ryann Derrama**Interior Color:** Brown**Inspection Location:** Los Angeles, CA **Client Name:** Motorenn Inc**Client Email:** service@motorenn.com**Make:** Porsche**VIN:** WP0BH2A96TS249440**Engine:** 6 cylinder**Inspector Phone:****Exterior Color:** Green**Seller:** Motorenn Inc**Model:** 911**Body Style:** Coupe**Drive Type:** AWD**Inspector Email:**

G = Good F = Fair P = Poor

G F P

Interior

- | | | | |
|-------------------------------------|--------------------------|--------------------------|---|
| ☒ | ☐ | ☐ | 1. Fuel Door Release |
| ☒ | ☐ | ☐ | 2. Hood Release |
| ☒ | ☐ | ☐ | 3. Trunk Lid Release |
| ☒ | ☐ | ☐ | 4. Air Bags |
| ☒ | ☐ | ☐ | 5. Tilt/Telescoping Steering Wheel |
| ☒ | ☐ | ☐ | 6. Steering Wheel Controls |
| ☒ | ☐ | ☐ | 7. Horn |
| ☒ | ☐ | ☐ | 8. Windshield Wiper Operation/Controls |
| ☒ | ☐ | ☐ | 9. Windshield Washer Operation/Controls |
| ☒ | ☐ | ☐ | 10. Instrument Panel |
| ☒ | ☐ | ☐ | 11. Warning Lights |
| ☒ | ☐ | ☐ | 12. Warning Chimes |
| ☒ | ☐ | ☐ | 13. Air Conditioning |
| ☒ | ☐ | ☐ | 14. Heating System |
| ☒ | ☐ | ☐ | 15. Defogger/Defroster |
| ☒ | ☐ | ☐ | 16. Clock |
| ☒ | ☐ | ☐ | 17. Radio |
| ☒ | ☐ | ☐ | 18. Audio Player |
| ☒ | ☐ | ☐ | 19. Speakers |
| ☒ | ☐ | ☐ | 20. Lighter/Power Outlet(s) |
| ☒ | ☐ | ☐ | 21. Interior Courtesy/Map/Dome Light |
| ☒ | ☐ | ☐ | 22. Glove Box |
| ☒ | ☐ | ☐ | 23. Glove Box Light |
| ☒ | ☐ | ☐ | 24. Center Console |
| ☒ | ☐ | ☐ | 25. Sun Visors |
| ☒ | ☐ | ☐ | 26. Sun Visors Lights |
| ☒ | ☐ | ☐ | 27. Vanity Mirrors |
| ☒ | ☐ | ☐ | 28. Inside Rear View Mirror |
| ☒ | ☐ | ☐ | 29. Armrests |

G F P

Interior

- | | | | |
|-------------------------------------|--------------------------|--------------------------|---------------------------------------|
| ☒ | ☐ | ☐ | 30. Outside Mirror Operation/Controls |
| ☒ | ☐ | ☐ | 31. Door Locks Manual |
| ☒ | ☐ | ☐ | 32. Door Locks Automatic |
| ☒ | ☐ | ☐ | 33. Child Safety Locks |
| ☒ | ☐ | ☐ | 34. Window Controls |
| ☒ | ☐ | ☐ | 35. Door Handles |
| ☒ | ☐ | ☐ | 36. Heated/Cooled Seats |
| ☒ | ☐ | ☐ | 37. Seats |
| ☒ | ☐ | ☐ | 38. Seat Controls |
| ☒ | ☐ | ☐ | 39. Headrest |
| ☒ | ☐ | ☐ | 40. Seat Belts |
| ☒ | ☐ | ☐ | 41. Sunroof/Moonroof |
| ☒ | ☐ | ☐ | 42. Convertible Top |
| ☒ | ☐ | ☐ | 43. Headliner |
| ☒ | ☐ | ☐ | 44. Carpet |
| ☒ | ☐ | ☐ | 45. Floor Mats |
| ☒ | ☐ | ☐ | 46. Interior Trim |
| ☒ | ☐ | ☐ | 47. Door Panels |
| ☒ | ☐ | ☐ | 48. Luggage Compartment |
| ☒ | ☐ | ☐ | 49. Trunk Light |
| ☒ | ☐ | ☐ | 50. Jack and Tool Kit |

Exterior

- | | | | |
|-------------------------------------|--------------------------|--------------------------|--------------------|
| ☒ | ☐ | ☐ | 51. Windshield |
| ☒ | ☐ | ☐ | 52. Wiper Blades |
| ☒ | ☐ | ☐ | 53. Windows |
| ☒ | ☐ | ☐ | 54. Rear Window |
| ☒ | ☐ | ☐ | 55. Mirrors |
| ☒ | ☐ | ☐ | 56. Head Lights |
| ☒ | ☐ | ☐ | 57. High Beams |
| ☒ | ☐ | ☐ | 58. Parking Lights |
| ☒ | ☐ | ☐ | 59. Turn Signals |

G F P

Exterior

- | | | | |
|-------------------------------------|--------------------------|--------------------------|--------------------------|
| ☒ | ☐ | ☐ | 60. Taillights |
| ☒ | ☐ | ☐ | 61. Brake Lights |
| ☒ | ☐ | ☐ | 62. Hazards |
| ☒ | ☐ | ☐ | 63. License Plate Lights |
| ☒ | ☐ | ☐ | 64. Reverse Lights |
| ☒ | ☐ | ☐ | 65. Fog Lights |
| ☒ | ☐ | ☐ | 66. Running Lights |
| ☒ | ☐ | ☐ | 67. Side Marker Lights |
| ☒ | ☐ | ☐ | 68. Body Panels |
| ☒ | ☐ | ☐ | 69. Front Bumper |
| ☒ | ☐ | ☐ | 70. Grille |
| ☒ | ☐ | ☐ | 71. Hood |
| ☒ | ☐ | ☐ | 72. Rear Bumper |
| ☒ | ☐ | ☐ | 73. Rear Hatch |
| ☒ | ☐ | ☐ | 74. Trunk |
| ☒ | ☐ | ☐ | 75. Left Front Fender |
| ☒ | ☐ | ☐ | 76. Left Front Door |
| ☒ | ☐ | ☐ | 77. Left Rear Fender |
| ☒ | ☐ | ☐ | 78. Left Rear Door |
| ☒ | ☐ | ☐ | 79. Right Rear Fender |
| ☒ | ☐ | ☐ | 80. Right Rear Door |
| ☒ | ☐ | ☐ | 81. Right Front Fender |
| ☒ | ☐ | ☐ | 82. Right Front Door |
| ☒ | ☐ | ☐ | 83. Roof |
| ☒ | ☐ | ☐ | 84. Roof Rack |
| ☒ | ☐ | ☐ | 85. Trim |
| ☒ | ☐ | ☐ | 86. Fuel Door |
| ☒ | ☐ | ☐ | 87. Paint |

Tires

- | | | | |
|-------------------------------------|--------------------------|--------------------------|---------------------|
| ☒ | ☐ | ☐ | 88. Left Front Tire |
| ☒ | ☐ | ☐ | 89. Left Rear Tire |
| ☒ | ☐ | ☐ | 90. Right Rear Tire |



G F P

Tires

- ☒ ☐ ☐ 91. Right Front Tire
☐ ☐ ☐ 92. Spare Tire
☒ ☐ ☐ 93. Wheels
☒ ☐ ☐ 94. Wheel Lug Nuts

Underbody

- ☒ ☐ ☐ 95. Frame
☒ ☐ ☐ 96. Overall Underbody Condition
☒ ☐ ☐ 97. Exhaust System
☒ ☐ ☐ 98. Catalytic Converter
☒ ☐ ☐ 99. Transmission Mounts
☒ ☐ ☐ 100. Transmission
☒ ☐ ☐ 101. Differential/Drive Axle
☒ ☐ ☐ 102. Universal Joints/CV Joints/Boots
☒ ☐ ☐ 103. Power Steering
☒ ☐ ☐ 104. Suspension
☒ ☐ ☐ 105. Tie-Rods/Idler Arm
☒ ☐ ☐ 106. Sway Bars
☒ ☐ ☐ 107. Springs
☒ ☐ ☐ 108. Shocks
☒ ☐ ☐ 109. Control Arms
☒ ☐ ☐ 110. Ball Joints/Bushings
☒ ☐ ☐ 111. Rotors/Drums
☒ ☐ ☐ 112. Calipers
☒ ☐ ☐ 113. Parking Brake
☒ ☐ ☐ 114. Brake Pads
☒ ☐ ☐ 115. Brake Lines/Hoses/Fittings

Underhood

- ☒ ☐ ☐ 116. Engine Oil
☒ ☐ ☐ 117. Brake Fluid
☒ ☐ ☐ 118. Coolant
☒ ☐ ☐ 119. Power Steering Fluid
☒ ☐ ☐ 120. Transmission Fluid
☒ ☐ ☐ 121. Washer Fluid
☒ ☐ ☐ 122. Transfer Case Fluid
☒ ☐ ☐ 123. Engine Mounts
☒ ☐ ☐ 124. Overall Engine Condition

G F P

Underhood

- ☒ ☐ ☐ 125. Engine Belts
☒ ☐ ☐ 126. Engine Hoses/Lines/Fittings
☒ ☐ ☐ 127. Radiator
☒ ☐ ☐ 128. Water Pump
☒ ☐ ☐ 129. Coolant Recovery Tank
☒ ☐ ☐ 130. Coolant Fans/Clutches/Motors
☒ ☐ ☐ 131. Coolant Hoses
☒ ☐ ☐ 132. Wiring
☒ ☐ ☐ 133. Starter Operation
☒ ☐ ☐ 134. Ignition Operation
☒ ☐ ☐ 135. Battery
☒ ☐ ☐ 136. Alternator
☒ ☐ ☐ 137. Air Filter
☒ ☐ ☐ 138. Fuel System Operation

Road Test

- ☒ ☐ ☐ 139. Starting
☒ ☐ ☐ 140. Idling
☒ ☐ ☐ 141. Engine Noise
☒ ☐ ☐ 142. Throttle
☒ ☐ ☐ 143. Transmission Shift
☒ ☐ ☐ 144. Clutch Operation
☒ ☐ ☐ 145. Accelerating
☒ ☐ ☐ 146. Steering Alignment
☒ ☐ ☐ 147. Power Steering
☒ ☐ ☐ 148. Cruise Control
☒ ☐ ☐ 149. Braking
☒ ☐ ☐ 150. ABS (Anti-Lock Braking System)
☒ ☐ ☐ 151. Body/Suspension

Additional Notes

152. Additional Notes:



Comments

- 88. Left Front Tire 10/32 3425
- 89. Left Rear Tire 8/32 3725
- 90. Right Rear Tire 8/32 4525
- 91. Right Front Tire 10/32 3425
- 114. Brake Pads Front Pads 95%
Rear Pads 95%
- 116. Engine Oil Next service due 02/2027