MOTORENN 151-POINT INSPECTION

MOTORENN

MAKE: Lucid MODEL: Air YEAR: VIN: 5179

	VEHICLE HISTORY	CHECK OFF
1	Matching vins	
2	Clean Carfax report	
3	No accidents	
4	No salvage/lemon title	
5	Maintenance records	
6	No open recalls	

NOTES :

	VEHICLE SERVICE	CHECK OFF
7	Engine oil and filter (If within 3 months or 2500 miles of service interval or no service records exist)	
8	Engine air filter (If within 3 months or 2500 miles of service interval or no service records exist)	
9	Cabin air filter (If within 3 months or 2500 miles of service interval or no service records exist)	
10	Brake fluid	
11	Coolant	
12	Transmission fluid	
13	Differential fluid	
14	Brake pads	
15	Brake rotors	
16	Wiper blades	
17	Tires	

NOTES :

	FACTORY ITEMS	CHECK OFF
18	Key check (Number)	
19	Original window sticker	
20	Original manuals	✓
21	Factory floor mats	✓

NOTES :

	AFTERMARKET PARTS	CHECK OFF
22	Factory exhaust	
23	Factory wheels	
24	Factory floor mats	
25	Factory audio unit	

	AFTERMARKET PARTS (CONT.)	CHECK OFF
26	Factory seats	
27	Any other Items?	

NOTES :

	ROAD TEST	CHECK OFF
28	Starting	
29	No idle at vibration	
30	No abnormal engine noise	
31	Smooth acceleration	
32	Engine operating temperature	
33	Smoothness in drivability	
34	Shifting smoothness	
35	No clutch slippage (Manuals)	
36	Manual transmission operation	
37	No transaxle noise	
38	No transmission noise	
39	No CV joint/drive axle noise	
40	Braking straight	
41	No brake noise	
42	Parking brake operation	
43	Steering effort (No drifting)	
44	No steering wheel play	
45	Cruise control operation	
46	Horn operation	
47	No excessive wind noise/squeaks/rattles	
48	Speedometer operation	
49	Heater/defroster operation	
50	A/C cooling performance	
51	No steering wheel vibration	
52	No body/suspension noise	

NOTES :

	UNDERHOOD	CHECK OFF
53	Battery (Condition, age, charge)	
54	Alternator (Belt condition, charging)	
55	Water pump (No leaks, no noise)	
56	Fuel System operation (Leaks)	
57	Radiator (No leaks, no damage)	
58	A/C condenser (No corrosion)	
59	Cooling fan operation	
60	Coolant hoses	

	UNDERHOOD (CONT.)	CHECK OFF
61	Engine mounts	
62	Transmission mounts	
63	Engine (No oil leaks)	
64	No transmission leaks	
65	No coolant leaks	
66	No CV joint and boot leaks or cracks	
67	Suspension height	
68	Bushing condition	
69	No power steering rack leakage	
70	Exhaust system condition	
71	Emissions compliant	
72	Engine bay clean	

NOTES :

	EXTERIOR	CHECK OFF
73	No wheel/rim damage	✓
74	Valve stem condition	✓
75	Valve stem cover present	✓
76	Wheel lug nuts properly torqued	✓
77	Locking wheel lug nut key (If applicable)	
78	Spare tire condition	N/A
79	Headlights high/low beam	✓
80	Brake lights	✓
81	Turn signals	✓
82	Parking lamps	
83	Fog lights	
84	Running lights	
85	License plate light	✓
86	Tail lights	✓
87	Back-up lights	✓
88	Emergency flasher	✓
89	Sunroof glass condition	✓
90	Side mirror condition	✓
91	Grille condition	✓
92	Drivers side front fender condition	✓
93	Driver side doors condition	✓
94	Drivers side rear quarter panel condition	✓
95	Passengers side front fender condition	✓
96	Passengers side doors condition	✓
97	Passengers side rear quarter panel condition	✓

NOTES :

MOTORENN 151-POINT INSPECTION

MOTORENN

MAKE: Lucid	MODEL:	YEAR:	VIN: 5179

	EXTERIOR (CONT.)	CHECK OFF
98	Front bumper condition	✓
99	Hood condition	✓
100	Trunk condition	✓
101	Rear bumper condition	✓
102	Roof paint condition	✓

NOTES :

	INTERIOR	CHECK OFF
104	No water leaks inside	
105	Fuel gauge operation	✓
106	Temp gauge operation	
107	All warning lights illuminated with ignition on	
108	Dash light operation	✓
109	Audio system function	✓
110	Bluetooth operations	
111	Satellite radio operation	
112	Steering wheel controls	✓
113	Navigation operation	
114	Rear camera operation	
115	Clock operation	✓
116	Steering wheel tilt operation	
117	Sunroof operation	
118	Sunshade operation	
119	Headliner condition	
120	Cigarette lighter operation	
121	Alarm/theft system operation	✓
122	SRS airbags condition	
123	Outside mirror operation (Left and right)	✓
124	Rearview mirror operation	
125	Window operation	✓
126	Door lock operation	✓
127	Seat belt operation	✓
128	Seat upholstery condition	✓
129	Power seat operation	✓
130	Seat heater operation	✓
131	Seat cooler operation	✓
132	Headrest movement operation	
133	Rear defrost operation	✓

NOTES :

Battery gauge

	INTERIOR (CONT.)	CHECK OFF
134	Inside light operation	✓
135	Warning chime operation	
136	Glove box and light operation	✓
137	Luggage compartment tools present	
138	Trunk lid release and light operation	✓
139	Liftgate operation	
140	Fuel door release	
141	Hood release operation	✓
142	No interior odors	✓

NOTES :

	DETAILING	CHECK OFF
143	Carpets vacuumed	
144	Car washed	
145	Car polished and waxed	
146	Tire dressing applied	
147	Leather cleaned	
148	Engine compartment cleaned	
149	Trunk vacuumed	
150	Interior glass and trim wiped down	
151	Exterior glass wiped down	

NOTES :

NOTES :